Oil Field Environmental Incident Summary

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC
Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: SC-HOVING 154-98-1003H-1

Field Name: TRUAX Well File #: 22946

Date Incident:9/8/2015Time Incident:09:00Facility ID Number:County:WILLIAMSTwp:154Rng:98Sec:10Qtr:

Location Description:

Submitted By: Jason Henry Received By:

Contact Person: Jason Henry

3015 16th Street SW, Suite 20

Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Fire

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 0.5 Barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/21/2015 Clean Up Concluded: 9/15/2015

Risk Evaluation:

The fire remained on location and extinguished itself.

Areal Extent:

Approxmately 2,000 square feet - impacted topsoil and stained vegetation, southeast of location

Potential Environmental Impacts:

A mist of crude oil was carried off location to the southeast resulting in impacted topsoil and stained vegetation. There was no surface water observed in the vicinity of the release location.

Action Taken or Planned:

The impacted soil and vegetation on the southeast side of the location will be excavated and transported off-site for proper disposal.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

Updates

Date: 9/8/2015 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, a mist of crude oil was carried off location. Further followup needed.

Date: 9/11/2015 Status: Inspection Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On-site at 10:15 am. Weather is 48 degrees F, mostly sunny, wind 7mph NE. Discoloration on grass extending SE of flare pit approximately 100Ft X 20Ft. Follow up with company rep on clean-up plans.

Date: 8/1/2016 Status: No Further Action Requested Author: Washek, Sandi

Updated Oil Volume: 0.50 barrels

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 4:20 p.m. Weather was overcast with wind out of the SW at 10 mph, and temperature was 81 degrees F. The area of impact is located south of the flare pit area. The area has been scraped and replanted. The area has grown with good vegetation cover, and none of the vegetation appears stressed. No additional follow-up needed.